

Terra Cotta Garland South Pediment

The south-facing pediment exhibits the very worst of the stone decay found at this site. Using the panel from the northeast as a guide I produced a similar design in terra cotta, shown here in raw and fired states.



This photo was shot from below while mapping the drill pattern for the stainless anchor pins. The work is composed of twelve separate pieces to facilitate transport and installation.